	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comment s
1	BRS	L1	3203	turbine and battery	USPA T	2003/03/0 6 13:09	
2	BRS	L2	3948	turbine and battery	Т	2003/03/0 6 13:43	
3	BRS	L3	437	2 and boost\$4	Т	2003/03/0 6 13:43	
4	BRS	L4	13023 0	(bi two) near3 direction\$4	Т	2003/03/0 6 13:44	
5	BRS	L5	6088	boost adj buck)(Dc adj dc	T	2003/03/0 6 13:44	
6	BRS	L6	13575 8	4 5	T	2003/03/0 6 13:14	
7	BRS	ь7	67	3 and 6	T	2003/03/0 6 13:40	
8	BRS	L8	39	7 and inverter	T	2003/03/0 6 13:14	
9	BRS	L9	0	7 not 6	USPA T	2003/03/0 6 13:40	
10	BRS	L10	28	7 not 8	Т	2003/03/0 6 13:41	
11	BRS	L11	9	10 and transformer	USPA T	2003/03/0 6 13:41	
12	BRS	L12	696	turbine and battery	DERW ENT	2003/03/0 6 13:46	
13	BRS	L14	33103	(bi two) near3 direction\$4	DERW ENT	2003/03/0 6 13:47	
14	BRS	L15	6903	boost adj buck)(Dc adj dc	DERW ENT	2003/03/0 6 13:47	
15	BRS	L16	39599	14 15	DERW ENT	2003/03/0 6 13:45	
16	BRS	L17	2	16 and 13	DERW ENT	2003/03/0 6 13:45	
17	BRS	L18	232	turbine and battery	JPO	2003/03/0 6 13:54	
18	BRS	L19	29	18 and boost\$4	JPO	2003/03/0 6 13:46	
19	BRS	L20	21340	(bi two) near3 direction\$4	JPO	2003/03/0 6 13:47	
20	BRS	L21	3136	boost adj buck)(Dc adj dc	JPO	2003/03/0 6 13:47	
21	BRS	L22	24077	20 21	JPO	2003/03/0 6 13:48	
22	BRS	L23	0	22 and 19	JPO	2003/03/0 6 13:48	
23	BRS	L13	24	12 and boost\$4	DERW ENT	2003/03/0 6 13:48	
24	BRS	L24	97	turbine and battery	EPO	2003/03/0 6 14:36	